

# LDS probe maintenance

Accessory  A 70

**Purpose** **Accessory** connected using a self-closing quick release connector to the leak detector. Used when working with the sniffing test method.



Reminder : For the sniffing test method, take into account that the average helium concentration in air is approximately 5 ppm,  $\approx 5 \cdot 10^{-6}$  mbar. l/s.

## Probe assembly

Components  F 130

